

```

<?xml version="1.0" standalone="yes"?>
<TRACS_IMPORT>
  <ALCOTEST_VALUES>
    <SERIAL>ARAE-0022</SERIAL>
    <IP_ADRESS>10.81.193.44</IP_ADRESS>
    <DATE>12/05/2019</DATE>
    <TIME>03:55AM</TIME>
  </ALCOTEST_VALUES>
  <CALCHECK_1>
    <CAL_MESSUNG_2_MESSUNG_ERROR>0</CAL_MESSUNG_2_MESSUNG_ERROR>
    <CAL_MESSUNG_2_IR_AAK_NULLWERT_1>0.00</CAL_MESSUNG_2
_IR_AAK_NULLWERT_1>
    <CAL_MESSUNG_2_IR_AAK_MESSWERT>0.10</CAL_MESSUNG_2
_IR_AAK_MESSWERT>
    <CAL_MESSUNG_2_EC_AAK_MESSWERT>0.10</CAL_MESSUNG_2
_EC_AAK_MESSWERT>
    <CAL_MESSUNG_2_IR_AAK_NULLWERT_2>0.00</CAL_MESSUNG_2
_IR_AAK_NULLWERT_2>
    <ID_BLANK_TIME_BEFORE_2>03:48:34AM
12/05/2019</ID_BLANK_TIME_BEFORE_2>
    <ID_TIME_START_BLOW_2>--:--:-- --/--/-----
</ID_TIME_START_BLOW_2>
    <ID_TIME_MEAS_2>03:49:11AM 12/05/2019</ID_TIME_MEAS_2>
    <ID_BLANK_TIME_AFTER_2>03:49:43AM
12/05/2019</ID_BLANK_TIME_AFTER_2>
  </CALCHECK_1>
  <SUBJECT_TEST>
    <PROB_MESSUNG_2_MESSUNG_ERROR>57</PROB_MESSUNG_2
_MESSUNG_ERROR>
    <PROB_MESSUNG_2_IR_AAK_NULLWERT_1>0.00</PROB_MESSUNG_2
_IR_AAK_NULLWERT_1>
    <PROB_MESSUNG_2_IR_AAK_MESSWERT>--</PROB_MESSUNG_2
_IR_AAK_MESSWERT>
    <PROB_MESSUNG_2_EC_AAK_MESSWERT>--</PROB_MESSUNG_2
_EC_AAK_MESSWERT>
    <PROB_MESSUNG_2_IR_AAK_NULLWERT_2>--</PROB_MESSUNG_2
_IR_AAK_NULLWERT_2>
    <PROB_MESSUNG_2_BLAS_FEHLVERSUCHE>0</PROB_MESSUNG_2
_BLAS_FEHLVERSUCHE>
    <PROB_MESSUNG_2_BLAS_VOLUMEN>--</PROB_MESSUNG_2_BLAS_VOLUMEN>
    <PROB_MESSUNG_2_BLAS_ZEIT>--</PROB_MESSUNG_2_BLAS_ZEIT>
    <ID_BLANK_TIME_BEFORE_3>03:52:30AM
12/05/2019</ID_BLANK_TIME_BEFORE_3>
    <ID_TIME_START_BLOW_3>--:--:-- --/--/-----
</ID_TIME_START_BLOW_3>
    <ID_TIME_END_BLOW_3>--:--:-- --/--/-----</ID_TIME_END_BLOW_3>
    <ID_TIME_MEAS_3>03:52:39AM 12/05/2019</ID_TIME_MEAS_3>
    <ID_BLANK_TIME_AFTER_3>--:--:-- --/--/-----
</ID_BLANK_TIME_AFTER_3>
  </SUBJECT_TEST>
  <CALCHECK_2>
    <CAL_MESSUNG_3_MESSUNG_ERROR>--</CAL_MESSUNG_3_MESSUNG_ERROR>

```

```

    <CAL_MESSUNG_3_IR_AAK_NULLWERT_1>-</CAL_MESSUNG_3
_IR_AAK_NULLWERT_1>
    <CAL_MESSUNG_3_IR_AAK_MESSWERT>-</CAL_MESSUNG_3
_IR_AAK_MESSWERT>
    <CAL_MESSUNG_3_EC_AAK_MESSWERT>-</CAL_MESSUNG_3
_EC_AAK_MESSWERT>
    <CAL_MESSUNG_3_IR_AAK_NULLWERT_2>-</CAL_MESSUNG_3
_IR_AAK_NULLWERT_2>
    <ID_BLANK_TIME_BEFORE_4>--:--:-- --/--/-----
</ID_BLANK_TIME_BEFORE_4>
    <ID_TIME_START_BLOW_4>--:--:-- --/--/-----
</ID_TIME_START_BLOW_4>
    <ID_TIME_MEAS_4>--:--:-- --/--/-----</ID_TIME_MEAS_4>
    <ID_BLANK_TIME_AFTER_4>--:--:-- --/--/-----
</ID_BLANK_TIME_AFTER_4>
</CALCHECK_2>
<GENERAL_DATA>
    <ID_SERIAL_NO>ARAE-0022</ID_SERIAL_NO>
    <ID_SW_VERSION> 8321288 1.12.2</ID_SW_VERSION>
    <ID_START_TIME>03:43:07AM 12/05/2019</ID_START_TIME>
    <ID_END_TIME>03:52:41AM 12/05/2019</ID_END_TIME>
    <ID_LAST_CAL_DATE>07/24/2019</ID_LAST_CAL_DATE>
    <ID_AAK_ENDRESULT>REFUSAL</ID_AAK_ENDRESULT>
    <ID_TEST_COUNTER>760</ID_TEST_COUNTER>
    <ID_MEAS_PROC>1</ID_MEAS_PROC>
    <ID_CALIBRATION_COUNTER>82</ID_CALIBRATION_COUNTER>
    <ID_ERROR_PROTOKOLL>46</ID_ERROR_PROTOKOLL>
    <ID_TEST_GAS_TYPE>2</ID_TEST_GAS_TYPE>
    <ID_TEST_GAS_INLET>1</ID_TEST_GAS_INLET>
    <ID_TEST_GAS_CONC>25.00</ID_TEST_GAS_CONC>
    <ID_TEST_CFG_SENSOR>0</ID_TEST_CFG_SENSOR>
    <ID_DATA_INPUT_ON_OFF>1</ID_DATA_INPUT_ON_OFF>
    <ID_IR_AVERAGE>15501</ID_IR_AVERAGE>
    <ID_EC_SENSOR_OFFSET>112</ID_EC_SENSOR_OFFSET>
    <ID_HOSE_TEMP>46.7</ID_HOSE_TEMP>
    <ID_IR_SENSOR_TEMP>45.3</ID_IR_SENSOR_TEMP>
    <ID_INTERNAL_DEVICE_TEMP>38.6</ID_INTERNAL_DEVICE_TEMP>
    <ID_12V_VOLTAGE>12.0</ID_12V_VOLTAGE>
    <ID_3V_BACKUP_VOLTAGE>3.3</ID_3V_BACKUP_VOLTAGE>
    <ID_MS_SW_CRC>0x6581</ID_MS_SW_CRC>
    <ID_PRESSURE_DRY_GAS>0</ID_PRESSURE_DRY_GAS>
    <ID_DRY_GAS_LOT_NO>1057590</ID_DRY_GAS_LOT_NO>
    <ID_DRY_GAS_EXP_DATA>12/08/2021</ID_DRY_GAS_EXP_DATA>
</GENERAL_DATA>
<INPUT_VALUES>
    <UF_CASE_NUMBER>SY19-2229</UF_CASE_NUMBER>
    <ZERO_TOLERANCE_CASE>NO</ZERO_TOLERANCE_CASE>
    <TROOP>T</TROOP>
    <STATION>SYRACUSE</STATION>
    <ARREST_DATE>12/05/2019</ARREST_DATE>
    <ARREST_TIME>03:06AM</ARREST_TIME>
    <ARRESTING_MEM_LAST>RONDON</ARRESTING_MEM_LAST>

```

<ARRESTING_MEM_FIRST>JEANETTE</ARRESTING_MEM_FIRST>
<ARRESTING_MEM_MI>N</ARRESTING_MEM_MI>
<ARRESTING_MEM_SHIELD>1343</ARRESTING_MEM_SHIELD>
<SUBJECT_LAST_NAME>HILL</SUBJECT_LAST_NAME>
<SUBJECT_FIRST_NAME>HAILEY</SUBJECT_FIRST_NAME>
<SUBJECT_MI>E</SUBJECT_MI>
<SUBJECT_DOB>10/31/1975</SUBJECT_DOB>
<SUBJECT_AGE>44</SUBJECT_AGE>
<SUBJECT_GENDER>FEMALE</SUBJECT_GENDER>
<OPERATOR_LAST_NAME>HILLMAN</OPERATOR_LAST_NAME>
<OPERATOR_FIRST_NAME>BRADLEY</OPERATOR_FIRST_NAME>
<OPERATOR_MI>T</OPERATOR_MI>
<OPERATOR_SHIELD_NO>5291</OPERATOR_SHIELD_NO>
<OPERATOR_PERMIT_NO>35127</OPERATOR_PERMIT_NO>
<OPERATOR_PERMIT_EXP>06/24/2021</OPERATOR_PERMIT_EXP>
<SUBJECT_OBSERVED_20_MINUTES>YES</SUBJECT_OBSERVED_20
_MINUTES>
<TEST_20_MINUTES_PAST_ARREST>YES</TEST_20
_MINUTES_PAST_ARREST>
<REFUSAL_MIRANDA_READ>YES</REFUSAL_MIRANDA_READ>
</INPUT_VALUES>
</TRACS_IMPORT>